

ICR-1601 Firmware

RELEASE NOTES

FW code: eA8



ADVANTECH

Abstract

This document contains the changelog of all new features, fixes and other changes implemented in firmware. For detailed information about firmware of eA8 code, see the Configuration Manual for your router.

Firmware Details

- **Short firmware version code:** eA8
- **Full firmware version code:** IA2_eA8.0CN0
- **Release date:** February 6, 2020
- **Hardware compatibility:** This firmware is applicable only to routers of ICR-1601 family made by Advantech.

Changelog



Legend: Affected products are marked as shown below for every changelog item:

Affected product

Not affected product

SNMP OID is changed

ICR-1601G

ICR-1601W

SNMP OID .1.3.6.1.4.1.10297.204.102.1.4.1.3.5.0 is changed to LAN MAC without "-". Trap info will include this OID.

Fixed EC25-AU connecting

ICR-1601G

ICR-1601W

Fixed issues with connecting of EC25-AU cellular module.